

USED TIRE INVENTORY

| Lot # | Size | Ply | Tread % | Brand | Price | Notes |
|-------|-----------|--------|---------|------------------------------|-----------|--|
| 24 | 11.2-28 | 4 | 80% | Goodyear | \$ 250.00 | On R-rear Ford 8n south side by fence |
| 11 | 13.6-28 | 6 | 70% | Powermark | \$ 250.00 | 2nd row, on WD 45 AC |
| 36 | 13.6-36 | 4 | 30% | Farm Tractor Tire | \$ 200.00 | On rim, east end tractor yard |
| 12 | 13.6-38 | 6 | 50% | Safemark | \$ 200.00 | on M farmall, 2nd row |
| 25 | 13.6-38 | 4 | 50% | Firestone | \$ 175.00 | Good tread, on H rim by tractor, south fence |
| 20 | 16.9 R 26 | 1 Star | 50% | Firestone | \$ 550.00 | on JD FWD waffle wheel, triangle area |
| 21 | 16.9 R 26 | 1 Star | 50% | Firestone | \$ 550.00 | w/tube, no wheel, triangle area |
| 39 | 16.9-24 | 6 | 75% | Goodyear R3 - diamond tread | \$ 300.00 | East end |
| 40 | 16.9-24 | 8 | 10% | | \$ 100.00 | East end |
| 41 | 16.9-24 | 12 | 15% | General | \$ 125.00 | East end on rim |
| 2 | 16.9-28 | | slick | | \$ 100.00 | terrace channel, triangle area |
| 34 | 16.9-28 | 6 | 60% | Safemark Multimile | \$ 375.00 | On L-rear, AC D17, 2nd row west end |
| 37 | 16.9-30 | 6 | 35% | G-year | \$ 250.00 | No rim, terrace channel west end |
| 3 | 16.9-34 | 6 | 50% | Alliance | \$ 275.00 | on spin out rim, east gate to tractor yard |
| 4 | 16.9-34 | 6 | 50% | Armstrong | \$ 275.00 | on spin out rim, east gate to tractor yard |
| 14 | 16.9-34 | 6 | 60% | Powermark | \$ 250.00 | on Oliver 1800 n fence |
| 33 | 18.4-26 | 8 | 60% | Powermark | \$ 400.00 | Triangle area above terrace, on rim |
| 13 | 18.4-34 | 6 | | Goodyear, good tread, cracks | \$ 150.00 | on Oliver 1800 n fence |
| 35 | 18.4-34 | 6 | 40% | Firestone | \$ 300.00 | On rim, east end tractor yard |
| 17 | 18.4-38 | 8 | 40% | Goodyear Dynatorque | \$ 300.00 | on dbl/bvl rim 3rd row by 2594 Case |
| 18 | 18.4-38 | 8 | 30% | Powermark | \$ 325.00 | on 8000 ford 4th row \$600 for pair 18&19 |
| 19 | 18.4-38 | 8 | 30% | Powermark | \$ 325.00 | on 8000 ford 4th row \$600 for pair 18&19 |
| 24 | 18.4-38 | 6 | 40% | Field Power | \$ 350.00 | on 9 hole JD dual wheel |
| 25 | 18.4-38 | 6 | 40% | Field Power | \$ 350.00 | on 9 hole JD dual wheel |
| 32 | 18.4R26 | 2 Star | 40% | Goodyear, no rim | \$ 400.00 | Triangle area above terrace |
| 7 | 18.4R38 | 1 Star | 50% | Firestone | \$ 600.00 | on JD step up, by 8640 |
| 8 | 18.4R38 | 1 Star | 50% | Firestone | \$ 600.00 | on JD step up, by 8640 |
| 10 | 18.4R38 | | 40% | Goodyear ultra torque | \$ 400.00 | terrace channel, triangle area |
| 22 | 18.4R38 | 1 Star | 75% | Goodyear DT10 | \$ 600.00 | on 9 hole JD dual wheel |
| 23 | 18.4R38 | 1 Star | 75% | Goodyear DT10 | \$ 600.00 | on 9 hole JD dual wheel |
| 30 | 18.4R42 | 2 Star | 40% | Titan | \$ 550.00 | on JD step wheels w/ 42" tires (\$1,600 for tires/wheels -30&31) |
| 31 | 18.4R42 | 2 Star | 30% | Goodyear | \$ 400.00 | on JD step up wheels w/42" tires, a few weather cracks on tread |

| | | | | | | |
|----|-----------|--------|-----|---------------------------|-----------|---|
| 1 | 20.8-34 | 8 | 50% | Goodyear Dyna Torque | \$ 400.00 | on JD dbl/bvl wheel, triangle area |
| 9 | 20.8-38 | 8 | 60% | Goodyear, deep tread, cut | \$ 400.00 | on dbl/bvl rim 3rd row by 2594 Case |
| 5 | 20.8R42 | 2 Star | 25% | Firestone | \$ 350.00 | bare tire, east gate to tractor yard |
| 6 | 20.8R42 | 2 Star | 25% | Firestone | \$ 300.00 | bare tire, east gate to tractor yard |
| 26 | 380/90R50 | 151A8 | 25% | Goodyear DT800 | \$ 350.00 | came off sprayer holding air (T/L), north end |
| 27 | 380/90R50 | 151A8 | 15% | Goodyear DT800 | \$ 200.00 | came off sprayer holding air (T/L), north end |
| 28 | 380/90R50 | 151A8 | 10% | Goodyear DT800 | \$ 175.00 | came off sprayer holding air (T/L), north end |
| 29 | 380/90R50 | 151A8 | 25% | Goodyear DT800 | \$ 350.00 | came off sprayer holding air (T/L), north end |